

Appendix H
Accident Data



Colour coding by SEVERITY

- ★ Fatal (1)
- Serious (8)
- ▼ Slight (36)

Dates searched between
30/08/2008 and 31/08/2013

This map is reproduced from Ordnance Survey material with the permission of Ordnance Survey on behalf of the Controller of Her Majesty's Stationery Office - Crown Copyright. Unauthorised reproduction infringes Crown copyright and may lead to prosecution or civil proceedings.
Working in partnership with Essex County Council
Licence No: 2013

Her Majesty's Office of Crown Copyright and Geomatics. Ordnance Survey (OS) is the UK's official mapping agency. Copyright and any other rights in the data shown on this page are reserved by Ordnance Survey.



Essex Highways

Essex Highways is a brand of Essex County Council. It is a registered trademark of Essex County Council.

DRAWING TITLE
Saffron Walden

SCALE 1 : 13750

DATE 08/11/2013

DRAWING No.

DRAWN BY

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I33660908 04/09/2008 Time 0800 Vehicles 2 Casualties 1 Serious
 E: 554227 N: 238429 First Road: B 1053 Road Type 2
 Speed limit: 30 Junction Detail: Slip Road Give way or controlled B 184
 Crossing: Control None Facilities: None within 50m Road surface Dry
 Daylight: no street lighting Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Failed to look properly	Vehicle 1	Very Likely	
2nd: Careless/Reckless/In a hurry	Vehicle 1	Possible	
3rd: Vehicle blind spot	Vehicle 1	Possible	
4th: Travelling too fast for conditions	Vehicle 1	Possible	
5th:			
6th:			

VEH 2 WAS WAITING AT THE JUNCTION OF EAST STREET & AUDLEY ROAD GIVING WAY TO A LORRY, WHEN VEH 1 COLLIDED WITH THE REAR OF VEH 2 CAUSING THE RIDER OF VEH 2 TO BE THROWN FROM HER PEDAL CYCLE & ONTO THE CARRIAGEWAY

Occurred on AUDLEY ROAD J/W EAST STREET

Vehicle Reference 1 Taxi/Private hire car Turning right
 Vehicle movement from W to E No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Mid Junction - on roundabout or T First impact Front Hit vehicle: 2
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 63 Male
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Vehicle Reference 2 Pedal Cycle Going ahead but held up
 Vehicle movement from W to E No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Jct Approach First impact Back Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 37 Female
 Not hit and run Breath test Not applicable
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 2 Age: 37 Female Driver/rider Severity: Serious
 Not a pupil Postcode Seatbelt

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I35941008 03/10/2008 Time 0950 Vehicles 1 Casualties 1 Slight
 E: 555739 N: 238409 First Road: B 1053 Road Type Single carriageway
 Speed limit: 60 Junction Detail: Not within 20m of junction Not applicable
 Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
 Daylight: no street lighting Raining without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Loss of control	Vehicle 1	Very Likely	
2nd: Inexperienced or learner driver/rider	Vehicle 1	Possible	
3rd:			
4th:			
5th:			
6th:			

VEH 1 WAS TRAVELLING ALONG RADWINTER ROAD FROM SEWARDS END TOWARDS SAFFRON WALDEN.VEH 1 HIT THE NEARSIDE MOUNTED THE BANK ON THE VERGE CAUSING THE VEH TO ROLL OVER ACROSS THE CARRIAGEWAY & RIGHT ITS SELF ON THE OPPOSITE SIDE OF THE ROAD

Occurred on RADWINTER ROAD 800m EAST OF J/W ELIZABETH WAY

Vehicle Reference 1 Car Going ahead left bend
 Vehicle movement from W to E No tow / articulation
 On main carriageway Overturned
 Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
 Hit object in road None Off road: None
 Nearside Age of Driver 18 Male
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 18 Male Driver/rider Severity: Slight
 Not a pupil Postcode Seatbelt

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I35741008 11/10/2008 Time 0150 Vehicles 1 Casualties 2 Serious
 E: 556410 N: 238184 First Road: B 1053 Road Type Single carriageway
 Speed limit: 60 Junction Detail: Not within 20m of junction Not applicable
 Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
 Darkness: no street lighting Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Impaired by alcohol	Vehicle 1	Very Likely	
2nd: Travelling too fast for conditions	Vehicle 1	Very Likely	
3rd:			
4th:			
5th:			
6th:			

VEHICLE 1 WAS TRAVELLING ALONG THE RADWINTER ROAD TOWARDS SAFFRON WALDEN FROM THE WALDEN ROAD DIRECTION. VEHICLE 1 FAILED TO NEGOTIATE A SLIGHT RIGHT HAND BEND AND LEFT THE ROAD ON THE NEARSIDE BEFORE ENDING UP SIDWAYS IN A DITCH.

Occurred on B1053 200 YARDS N/W JUNCTION WITH COLE END LANE.

Vehicle Reference 1 Car Going ahead right bend
 Vehicle movement from E to NW No tow / articulation
 On main carriageway Skidded
 Location at impact Not at, or within 20M of Jct First impact Nearside Hit vehicle:
 Hit object in road None Off road: Entered ditch
 Nearside Age of Driver 37 Male
 Not hit and run Breath test Failed to provide
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 35 Female Passenger Severity: Slight
 Not a pupil Postcode Seatbelt
 Front seat

Casualty Reference: 2 Vehicle: 1 Age: 37 Male Driver/rider Severity: Serious
 Not a pupil Postcode Seatbelt

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I40711108 05/11/2008 Time 1130 Vehicles 2 Casualties 1 Slight
 E: 553973 N: 238643 First Road: B 1052 Road Type Single carriageway
 Speed limit: 30 Junction Detail: Not within 20m of junction Not applicable
 Crossing: Control None Facilities: Zebra crossing Road surface Wet/Damp
 Daylight:street lights present Raining without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Failed to look properly	Vehicle 1	Very Likely	
2nd: Slippery road (due to weather)	Vehicle 1	Very Likely	
3rd:			
4th:			
5th:			
6th:			

VEH 2 WAS STATIONARY AT A PEDESTRIAN CROSSING WHEN VEH 1 RODE INTO THE REAR OF VEH 2.

Occurred on COMMON HILL 200 YARDS NORTH OF J/W CATES CORNER

Vehicle Reference 1 Motorcycle 50cc and under Going ahead other
 Vehicle movement from N to S No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle: 2
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 21 Male
 Not hit and run Breath test Not requested
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 21 Male Driver/rider Severity: Slight
 Not a pupil Postcode Seatbelt

Vehicle Reference 2 Car Going ahead but held up
 Vehicle movement from N to S No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Not at, or within 20M of Jct First impact Back Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 43 Female
 Not hit and run Breath test Not requested
 Driver Postcode: VRM:

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I02160109 22/01/2009 Time 1530 Vehicles 2 Casualties 1 Slight
 E: 553649 N: 237961 First Road: B 1052 Road Type Single carriageway
 Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
 Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
 Daylight:street lights present Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Junction overshoot	Vehicle 2	Very Likely	
2nd: Loss of control	Vehicle 2	Very Likely	
3rd: Failed to look properly	Vehicle 2	Possible	
4th: Nervous/Uncertain/Panic	Vehicle 2	Possible	
5th:			
6th:			

VEH 2 TRAVELLING NORTH APPROACHED JUN AT LITTLE LARCH MOUTH WITH LONDON RD, FAILED TO STOP AT UN AND COLLIDED WITH VEH 1 THAT WAS TRAVELLING WEST ON LODNON RD. VEH 2 THEN ACCELERATED AND STRUCK FRONT WALL ON OPP SIDE OF THE RD.

Occurred on J/W LITTLE LARCH MOUTH & LONDON RD

Vehicle Reference 1 Car Going ahead other
 Vehicle movement from E to W No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 27 Male
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 22 Female Passenger Severity: Slight
 Not a pupil Postcode Seatbelt
 Back seat

Vehicle Reference 2 Car Stopping
 Vehicle movement from S to N No tow / articulation
 On main carriageway Skidded
 Location at impact Jct Approach First impact Front Hit vehicle: 1
 Hit object in road None Off road: Oth perm objects
 Straight ahead at Jun Age of Driver 85 Male
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I06510209 21/02/2009 Time 0153 Vehicles 1 Casualties 1 Slight
 E: 553810 N: 238373 First Road: U Road Type 2
 Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
 Crossing: Control None Facilities: None within 50m Road surface Dry
 Darkness: street lights present and lit Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation		Participant:	Confidence:
Factor:			
1st:	Failed to look properly	Casualty 1	Possible
2nd:	Impaired by alcohol	Vehicle 1	Very Likely
3rd:			
4th:			
5th:			
6th:			

DRIVER OF VEH 1 TURNED RIGHT INTO GOLD STREET WHERE A PEDESTRIAN STEPPED INTO THE ROAD IN FRONT OF HER AND WAS HIT BY THE FRONT OF THE VEHICLE

Occurred on OUTSIDE OLD ENGLISH GENTLEMAN PUB, GOLD STREET

Vehicle Reference 1 Car Stopping
 Vehicle movement from Park to Parked No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Cleared junction or waiting/parke First impact Front Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 24 Female
 Not hit and run Breath test Positive
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 22 Female Pedestrian Severity: Slight
 Not a pupil Postcode Seatbelt
 In carr elsewhere W bound
 Driver's offside

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I09130309 20/03/2009 Time 1300 Vehicles 2 Casualties 2 Slight
 E: 553754 N: 238081 First Road: B 1052 Road Type 1
 Speed limit: 30 Junction Detail: Roundabout Give way or controlled Unclassified
 Crossing: Control None Facilities: None within 50m Road surface Dry
 Daylight:street lights present Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Disobeyed Give Way or Stop sign or markings	Vehicle 1	Very Likely	
2nd: Loss of control	Vehicle 1	Very Likely	
3rd:			
4th:			
5th:			
6th:			

VEH 1 WAS TRAVELLING ALONG DEBDEN ROAD AND STOPPED AT THE ROUNDABOUT J/W LONDON ROAD, GIVING WAY TO TRAFFIC TO THE RIGHT. VEH 2 APPROACHED ROUNDABOUT FROM THE LONDON ROAD. VEH 1 EMERGED ONTO THE ROUNDABOUT IN FRONT OF VEH 2 AFTER DRIVERS FOOT SLIPPED FROM BRAKE ONTO ACCELERATOR. VEH 1 COLLIDED WITH N/S OF VEH 2.

Occurred on LONDON ROAD J/W DEBDEN ROAD SAFFRON WALDEN

Vehicle Reference 1 Car Stopping
 Vehicle movement from W to E No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Entering roundabout First impact Front Hit vehicle: 2
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 36 Female
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 12 Female Passenger Severity: Slight
 Not a pupil Postcode Seatbelt
 Front seat

Vehicle Reference 2 Car Going ahead other
 Vehicle movement from N to S No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Entering roundabout First impact Nearside Hit vehicle: 1
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 36 Female
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Casualty Reference: 2 Vehicle: 2 Age: 36 Female Driver/rider Severity: Slight
 Not a pupil Postcode Seatbelt

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I13320409 21/04/2009 Time 1715 Vehicles 2 Casualties 1 Slight
 E: 553814 N: 237956 First Road: U Road Type Single carriageway
 Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
 Crossing: Control None Facilities: None within 50m Road surface Dry
 Daylight:street lights present Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation		Participant:	Confidence:
Factor:			
1st:	Failed to look properly	Vehicle 1	Possible
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 WAS AT JCT ON STATION RD WITH DEBDEN RD, VEH HAS PARKED, GEBAN TO PULL OUT AND WAS LOOKING UP DEBDEN RD. A CYCLIST WAS CYCLING U[P THE ROAD AND SAKED AT THE CAR NOT TO PULL OUT, VEH DID NOT KNOW AND PULLED OTU KNOCKING CYCLIST OFF HIS BIKE.

Occurred on STATION RD J/W DEBDEN RD

Vehicle Reference 1 Car Turning right
 Vehicle movement from W to SE No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Jct Approach First impact Front Hit vehicle: 2
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 28 Male
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Vehicle Reference 2 Pedal Cycle Going ahead other
 Vehicle movement from W to SE No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Jct Approach First impact Offside Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 36 Male
 Not hit and run Breath test Not requested
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 2 Age: 36 Male Driver/rider Severity: Slight
 Not a pupil Postcode Seatbelt

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I17280609 06/06/2009 Time 1155 Vehicles 2 Casualties 1 Fatal
 E: 553898 N: 238180 First Road: B 184 Road Type 2
 Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
 Crossing: Control None Facilities: Zebra crossing Road surface Dry
 Daylight:street lights present Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation			
	Factor:	Participant:	Confidence:
1st:	Sudden braking	Vehicle 1	Very Likely
2nd:	Failed to judge other persons path or speed	Vehicle 1	Possible
3rd:	Failed to judge other persons path or speed	Vehicle 2	Possible
4th:	Uncorrected, defective eyesight	Vehicle 1	Possible
5th:	Uncorrected, defective eyesight	Vehicle 2	Possible
6th:			

VEH 1 TRAVELLING AUDLEY RD FROM DIRECTION OF RADWINTER TOWARDS SAFFRON HIGH ST VEH 2 CROSSING AUDLEY RD NORTH TO SOUTH. VEH 1 COLLIDES FRONT OFFSIDE WITH NEARISDE OF VEH 2.

Occurred on AUDLEY RD 11M WEST OF J/W STATION STREET

Vehicle Reference 1 Car Going ahead other
 Vehicle movement from W to E No tow / articulation
 On main carriageway Skidded
 Location at impact Cleared junction or waiting/parke First impact Front Hit vehicle: 2
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 83 Male
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Vehicle Reference 2 Other non motor Going ahead other
 Vehicle movement from S to N No tow / articulation
 On main carriageway Skidded and overturned
 Location at impact Jct Approach First impact Nearside Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 95 Female
 Not hit and run Breath test Not applicable
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 2 Age: 95 Female Driver/rider Severity: Fatal
 Not a pupil Postcode Seatbelt

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I21720709 02/07/2009 Time 0830 Vehicles 2 Casualties 1 Slight
 E: 553842 N: 238452 First Road: U Road Type 2
 Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
 Crossing: Control None Facilities: None within 50m Road surface Dry
 Daylight: no street lighting Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: Elsewhere DfT Special Projects:

Causation		Participant:	Confidence:
Factor:			
1st:	Failed to judge other persons path or speed	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 2 COMING OUT OF MARKET SQUARE TOWARDS HILL ST VEH 1 COMING OUT OF BUTCHERS ROW INTO MARKET ST COLLIDING WITH VEH 2 DRIVERS SIDE CAUSING DAMAGE

Occurred on MARKET ROW J/W HIGH ST

Vehicle Reference 1 Car Turning right
 Vehicle movement from N to S No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Jct Approach First impact Offside Hit vehicle: 2
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 48 Male
 Not hit and run Breath test Driver not contacted
 Driver Postcode: VRM:

Vehicle Reference 2 Car Turning left
 Vehicle movement from E to S No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Jct Approach First impact Front Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 26 Female
 Not hit and run Breath test Driver not contacted
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 2 Age: 26 Female Driver/rider Severity: Slight
 Not a pupil Postcode Seatbelt

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I25870809 13/08/2009 Time 1922 Vehicles 2 Casualties 2 Slight
 E: 553744 N: 238336 First Road: B 184 Road Type Single carriageway
 Speed limit: 30 Junction Detail: Not within 20m of junction Not applicable
 Crossing: Control None Facilities: None within 50m Road surface Dry
 Daylight:street lights present Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Road layout (eg bend, hill etc.)	Vehicle 001	Possible	
2nd: Defective brakes	Vehicle 001	Possible	
3rd: Failed to look properly	Vehicle 001		
4th:			
5th:			
6th:			

VEH 1 WAS TRAVELLING DOWN SAFFRON WALDEN HIGH STREET TOWARDS THE TRAFFIC LIGHTS VEH 2 WAS STATIONARY AT THE LIGHTS WITH HAND BRAKE APPLIED. VEH 1 APPLIED BRAKES BUT DID NOT STOP IN TIME AND WENT INTO THE BACK OF VEH 2. VEH 1 AIR BAGS DEPLOYED AND T HE BUMPED TO VEH WAS DAMAGED ASWELL AS THE BONNET BUCKING.

Occurred on HIGH STREET 50M FROM JW GEORGE STREET

Vehicle Reference 1 Car Starting
 Vehicle movement from N to S No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 40 Male
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 40 Male Driver/rider Severity: Slight
 Not a pupil Postcode Seatbelt

Vehicle Reference 2 Car Stopping
 Vehicle movement from N to S No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Not at, or within 20M of Jct First impact Back Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 23 Female
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Casualty Reference: 2 Vehicle: 2 Age: 23 Female Driver/rider Severity: Slight
 Not a pupil Postcode Seatbelt

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I31790909 30/09/2009 Time 1155 Vehicles 3 Casualties 1 Serious
 E: 555028 N: 238473 First Road: B 1053 Road Type Single carriageway
 Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
 Crossing: Control None Facilities: None within 50m Road surface Dry
 Daylight:street lights present Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Failed to look properly	Vehicle 001	Very Likely	
2nd: Careless/Reckless/In a hurry	Vehicle 001	Possible	
3rd:			
4th:			
5th:			
6th:			

VEH 2 TRAVELLING SAFFRON TOWARDS RADWINTER. VEH 3 STATIC AT JW HOSPITAL APPROACH ON RADWINTER ROAD FACING SAFFRON INDICATING RIGHT. VEH 1 DRIVES TO RADWINTER ROAD ALONG HOSPITAL APPROACH TO TURN RIGHT TOWARDS SAFFRON. VEH 2 IS STRUCK BY VEH 1 AS D RIVER PULLS OUT ONTO MAIN ROAD. VEH 2 RICOCHETS INTO SIDE OF VEH 3

Occurred on RADWINTER ROAD EAST BOUND AT JW HOSPITAL APPROACH

Vehicle Reference 1 Car Turning right
 Vehicle movement from N to W No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Cleared junction or waiting/parke First impact Front Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 40 Female
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Vehicle Reference 2 Car Going ahead other
 Vehicle movement from W to E No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Jct Approach First impact Nearside Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 31 Female
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 2 Age: 31 Female Driver/rider Severity: Serious
 Not a pupil Postcode Seatbelt

Vehicle Reference 3 Bus or coach Turning right
 Vehicle movement from E to N No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Jct Approach First impact Offside Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 31 Male
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I33221009 01/10/2009 Time 0820 Vehicles 2 Casualties 1 Slight
 E: 555229 N: 238434 First Road: B 1053 Road Type Single carriageway
 Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
 Crossing: Control None Facilities: None within 50m Road surface Dry
 Daylight:street lights present Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Disobeyed Give Way or Stop sign or markings	Vehicle 1	Very Likely	
2nd: Poor turn or manoeuvre	Vehicle 1	Possible	
3rd: Nervous/Uncertain/Panic	Vehicle 1	Possible	
4th: Disobeyed double white line	Vehicle 1	Possible	
5th: Distraction in vehicle	Vehicle 1	Possible	
6th: Failed to look properly	Vehicle 1	Very Likely	

VEH 1 TRAVELLING RADWINTER RD FROM DIRECTION OF SAFFRON WALDEN, STOPPED IN CENTRAK HATCHED AREA TO TURN RIGHJT INTO TESCO. VEH 1 SWERVES LEFT TO TRY AND AVOID COLLISION HOWEVER VEH 1 COLLIDES FRONT END WITH F/N/S OF VEH 2 WHICH ALSO COLLIDES WITH TRAFFIC ISLAND BOLLARD IN CENTRE OF TESCO ENTRY.

Occurred on RADWINTER RD B1053 J/W TESCO ENTRANCE

Vehicle Reference 1 Car Turning right
 Vehicle movement from W to S No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle: 2
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 29 Male
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Vehicle Reference 2 Car Going ahead other
 Vehicle movement from E to W No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Jct Approach First impact Nearside Hit vehicle:
 Hit object in road None Off road: Oth perm objects
 Nearside Age of Driver 44 Female
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 2 Age: 44 Female Driver/rider Severity: Slight
 Not a pupil Postcode Seatbelt

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I04040210 10/02/2010 Time 0756 Vehicles 2 Casualties 1 Slight
 E: 553560 N: 237842 First Road: B 1052 Road Type Single carriageway
 Speed limit: 60 Junction Detail: Not within 20m of junction Not applicable
 Crossing: Control None Facilities: None within 50m Road surface Frost/Ice
 Daylight: no street lighting Snowing without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Slippery road (due to weather)	Vehicle 1	Very Likely	
2nd: Loss of control	Vehicle 1	Very Likely	
3rd: Slippery road (due to weather)	Vehicle 2	Very Likely	
4th: Loss of control	Vehicle 2	Very Likely	
5th:			
6th:			

VEH 1 TRAVELLING ALONG THE NEWPORT ROAD FROM SAFFRON WALDEN IN THE GENERAL DIRECTION OF NEWPORT. VEH 2 TRAVELS BEHIND. VEH 1 LOOSES CONTROL AND ICY ROAD SURFACE, VEH 2 BRAKES BUT ALSO LOOSES CONTROL AND COLLIDES INTO REAR OF VEH 1.

Occurred on NEWPORT ROAD APPROX 50YRDS SAFFRON WALDEN SIDE J/W LONDON ROAD

Vehicle Reference 1 Car Going ahead other
 Vehicle movement from NE to SW No tow / articulation
 On main carriageway Skidded
 Location at impact Not at, or within 20M of Jct First impact Back Hit vehicle: 2
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 49 Female
 Not hit and run Breath test Not requested
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 49 Female Driver/rider Severity: Slight
 Not a pupil Postcode Seatbelt

Vehicle Reference 2 Car Stopping
 Vehicle movement from NE to SW No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle: 1
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 29 Male
 Not hit and run Breath test Not requested
 Driver Postcode: VRM:

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I06720310 05/03/2010 Time 0957 Vehicles 1 Casualties 1 Slight
 E: 556071 N: 238252 First Road: B 1053 Road Type Single carriageway
 Speed limit: 60 Junction Detail: Not within 20m of junction Not applicable
 Crossing: Control None Facilities: None within 50m Road surface Frost/Ice
 Daylight: no street lighting Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation			
	Factor:	Participant:	Confidence:
1st:	Careless/Reckless/In a hurry	Vehicle 1	Very Likely
2nd:	Loss of control	Vehicle 1	Possible
3rd:	Slippery road (due to weather)	Vehicle 1	
4th:			
5th:			
6th:			

VEH 1 DRIVING FROM RADWINTER TOWARDS SAFFRON WALDEN AT APPROXIMATELY 55MPH HIT AN ICY PATCH, CROSSED INTO OPPOSITE BANK AND ROLLED VEHICLE.

Occurred on RADWINTER ROAD APPROXIMATELY 500MTRS

Vehicle Reference 1 Car Going ahead right bend
 Vehicle movement from E to NW No tow / articulation
 On main carriageway Overturned
 Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
 Hit object in road None Off road: Oth perm objects
 Did not leave carr Age of Driver 18 Male
 Not hit and run Breath test Not requested
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 18 Male Driver/rider Severity: Slight
 Not a pupil Postcode Seatbelt

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I06390310 07/03/2010 Time 1505 Vehicles 2 Casualties 1 Serious
 E: 554343 N: 238666 First Road: U Road Type Single carriageway
 Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
 Crossing: Control None Facilities: None within 50m Road surface Dry
 Daylight:street lights present Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Loss of control	Vehicle 1	Very Likely	
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 HEADING EAST ALONG ASHDEN ROAD SAFFRON WALDEN IN GENERAL DIRECTION OF COMMERCIAL CENTRE. VEH2 IS PARKED BY SOUTH KERB FACING WEST. THE DRIVER FO VH 1 SUFFERS A MEDICAL CONDITION THAT CAUSED HIM TO LASH OUT. VEH 1 COLLIDES WITH VEH 2 AND BOTHVEH ICLES SUSTAIN DAMAGE AS LISTED. DRIVER OF VEH 1 ALSO SUSTAINS A MAJOR LACERATION TO THE TOP OF HIS HEAD. DRIVER OF VEH 1 TAKEN TO ADDENBROOKS TO HAVE HIS MEDICAL CONDITION AND HEAD WOUND.

Occurred on ASHDON ROAD 20M EAST J/W HIGHFIELDS, SAFFRON WALDEN, ESSEX

Vehicle Reference 1 Car Going ahead other
 Vehicle movement from W to E No tow / articulation
 On main carriageway Skidded
 Location at impact Cleared junction or waiting/parke First impact Front Hit vehicle: 2
 Hit object in road Parked Vehicle Off road: None
 Did not leave carr Age of Driver 80 Male
 Not hit and run Breath test Driver not contacted
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 80 Male Driver/rider Severity: Serious
 Not a pupil Postcode Seatbelt

Vehicle Reference 2 Car Parked
 Vehicle movement from Park to Parked No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Cleared junction or waiting/parke First impact Front Hit vehicle: 1
 Hit object in road None Off road: None
 Nearside Age of Driver Not traced
 Not hit and run Breath test Driver not contacted
 Driver Postcode: VRM:

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I34171010 16/10/2010 Time 1220 Vehicles 3 Casualties 1 Slight
 E: 554514 N: 238169 First Road: B 184 Road Type Single carriageway
 Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
 Crossing: Control None Facilities: None within 50m Road surface Dry
 Daylight:street lights present Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: Elsewhere DfT Special Projects:

Causation		Participant:	Confidence:
Factor:			
1st:	Impaired by alcohol	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 2 PROCEEDING ON THAXTED RD TOWARDS TOWN. VEH 3 STATIONARY IN OPPOSITE DIRECTION INDICATING TO TURN INTO VICTORIA AVE. VEH 1 HAS OVERTAKEN VEH 3 AT SPEED AND COLLIDED WITH DRVS SIDE OF VEH 2 CAUSING VEH 2 TO VEER INTO ROAD SIGN AT VICTORIA AVE.

Occurred on THAXTED RD J/W VICTORIA AVE

Vehicle Reference 1 Car Overtaking stat vehicle O/S
 Vehicle movement from N to S No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Jct Approach First impact Offside Hit vehicle: 2
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 26 Female
 Hit and run Breath test Positive
 Driver Postcode: VRM:

Vehicle Reference 2 Car Turning left
 Vehicle movement from S to N No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Jct Approach First impact Nearside Hit vehicle: 3
 Hit object in road None Off road: Road sign / ATS
 Nearside Age of Driver 48 Male
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 2 Age: 48 Male Driver/rider Severity: Slight
 Not a pupil Postcode Seatbelt

Vehicle Reference 3 Car Going ahead other
 Vehicle movement from S to N No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Jct Approach First impact Front Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 50 Female
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I39211110 25/11/2010 Time 2334 Vehicles 2 Casualties 1 Slight
 E: 553946 N: 238820 First Road: B 1052 Road Type Single carriageway
 Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
 Crossing: Control None Facilities: None within 50m Road surface Dry
 Darkness: street lights present and lit Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation			
	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Very Likely
2nd:	Junction overshoot	Vehicle 1	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEH 1 HAS OVERSHOT JCT OF CATONS LANE WITH LITTLE WALDEN RD AND PULLED INTO PATH OF VEH 2 TRAVELLING NORTHBOUND ON LITTLE WALDEN RD.

Occurred on LITTLE WALDEN RD J/W CATONS LANE

Vehicle Reference 1 Car Going ahead other
 Vehicle movement from S to N No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Jct Approach First impact Front Hit vehicle: 2
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 21 Female
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 21 Female Driver/rider Severity: Slight
 Not a pupil Postcode Seatbelt

Vehicle Reference 2 Car Going ahead other
 Vehicle movement from N to S No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Jct Approach First impact Front Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 26 Male
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I03990211 08/02/2011 Time 1005 Vehicles 1 Casualties 1 Slight
 E: 553721 N: 238406 First Road: B 184 Road Type Single carriageway
 Speed limit: 30 Junction Detail: Other Automatic traffic signal
 Crossing: Control None Facilities: Pelican, puffin, toucan etc. Road surface Dry
 Daylight:street lights present Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: Elsewhere DfT Special Projects:

	Causation		Participant:	Confidence:
Factor:				
1st:				
2nd:				
3rd:				
4th:				
5th:				
6th:				

PEDESTRIAN WALKING OUTSIDE A PAVEMENT TOWARDS GEORGE STREET. VEH 1 TRAVELLING SAME DIRECTION ON PASSING PEDESTRIAN N//S DOOR MIRROR STRUCK PEDESTRIAN ON REAR.

Occurred on HIGH STREET, 20 YRDS LONDON ROAD SIDE J/W GEORGE ST

Vehicle Reference 1 Car Going ahead other
 Vehicle movement from S to N No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Jct Approach First impact Did not impact Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver Not traced
 Hit and run Breath test Driver not contacted
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 43 Male Pedestrian Severity: Slight
 Not a pupil Postcode Seatbelt
 On footpath / verge N bound
 Movement U/K

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I22820211 17/02/2011 Time 1705 Vehicles 2 Casualties 1 Slight
 E: 554057 N: 238467 First Road: B 184 Road Type 2
 Speed limit: 30 Junction Detail: Not within 20m of junction Not applicable
 Crossing: Control None Facilities: None within 50m Road surface Dry
 Daylight:street lights present Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation			
	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Very Likely
2nd:	Failed to judge other persons path or speed	Vehicle 1	Possible
3rd:			
4th:			
5th:			
6th:			

VEH 2 WAS STATIONARY OUTSIDE THE POLICE STATION IN QUEUE OF TRAFFIC. VEH 1 HAS HIT VEH 2 IN THE REAR AT VERY LOW SPEED.

Occurred on OUTSIDE SAFFRON WALDEN POLICE STATION EAST STREET SAFFRON WALDEN 50 M J/W FA

Vehicle Reference 1 Car Stopping
 Vehicle movement from W to E No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle: 2
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 45 Female
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Vehicle Reference 2 Car Going ahead but held up
 Vehicle movement from W to E No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Not at, or within 20M of Jct First impact Back Hit vehicle: 1
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 29 Female
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 2 Age: 29 Female Driver/rider Severity: Slight
 Not a pupil Postcode Seatbelt

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I07920311 15/03/2011 Time 1320 Vehicles 1 Casualties 1 Slight
 E: 553716 N: 238437 First Road: B 184 Road Type Single carriageway
 Speed limit: 30 Junction Detail: Other Give way or controlled
 Crossing: Control None Facilities: None within 50m Road surface Dry
 Daylight:street lights present Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: Elsewhere DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Failed to look properly	Vehicle 1	Very Likely	
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 STATIONARY IN QUEUE OF TRAFFIC REVERSED SLIGHTLY TO ALLOW PASSAGE TO VEH TRAVELLING IN OPPOSITE DIRECTION AND STRUCK PEDESTRIAN IN ROAD BEHIND HIM.

Occurred on SAFFRON WALDEN, B184 HIGH STREET J/W KING STREET

Vehicle Reference 1 Car Reversing
 Vehicle movement from N to S No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Jct Approach First impact Back Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 56 Male
 Not hit and run Breath test Not requested
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 83 Male Pedestrian Severity: Slight
 Not a pupil Postcode Seatbelt
 In carr elsewhere W bound
 Driver's nearside

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I11970411 27/04/2011 Time 1302 Vehicles 2 Casualties 2 Serious
 E: 554980 N: 238835 First Road: U Road Type Unknown
 Speed limit: 60 Junction Detail: Not within 20m of junction Not applicable
 Crossing: Control None Facilities: None within 50m Road surface Dry
 Daylight: no street lighting Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Poor turn or manoeuvre	Vehicle 1	Possible	
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 TRAVELLING OUT OF SAFFRON WALDEN ALONG ASHDON ROAD TOWARDS REGATES LANE VEH 2 TRAVELLING TOWARDS SAFFRON WALDEN VEH 1 STARTS TO OVERTAKE CYCLIST AND ON HIS WAY ALONG VEH 2 COLLIDES WITH VEH 1S OFFSIDE REAR TYRE CAUSING VEH 2 TO HIT BANK BACKWARDS EXTENSIVE FRONT AND END DAMAGE TO VEH 2 MINOR DAMAGE TO VEH 1.

Occurred on 150 YRDS AFTER J/W ELIZABETH WAY, ON ASHDON ROAD

Vehicle Reference 1 Car Overtaking nearside
 Vehicle movement from W to E No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Not at, or within 20M of Jct First impact Offside Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 78 Male
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 78 Male Driver/rider Severity: Serious
 Not a pupil Postcode Seatbelt

Casualty Reference: 2 Vehicle: 1 Age: 72 Female Passenger Severity: Slight
 Not a pupil Postcode Seatbelt
 Front seat

Vehicle Reference 2 Goods over 3.5 tonnes and under 7.5 Going ahead left bend
 Vehicle movement from E to W No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 44 Male
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I14040511 11/05/2011 Time 0845 Vehicles 1 Casualties 1 Slight
 E: 554799 N: 238762 First Road: U Road Type Single carriageway
 Speed limit: 30 Junction Detail: Not within 20m of junction Not applicable
 Crossing: Control None Facilities: None within 50m Road surface Dry
 Daylight:street lights present Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: Elsewhere DfT Special Projects:

Causation			
	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Possible
2nd:	Failed to look properly	Casualty 1	Possible
3rd:	Failed to judge vehicles path or speed	Casualty 1	Possible
4th:	Passing too close to cyclist, horse rider or pedestrian	Vehicle 1	Possible
5th:	Nervous/Uncertain/Panic	Vehicle 1	Possible
6th:	Failed to judge other persons path or speed	Vehicle 1	Possible

VEH 1 WAS TRAVELLING EAST ALONG ASHDON ROAD. VEH 1 STOPPED TO ALLOW TRAFFIC IN OPPOSING DIRECTION TO PASS. PEDESTRIAN STEPPED OUT TO CROSS ROAD AT WHICH POINT VEH 1 MOVED FORWARD AND FRONT NEARSIDE MADE MIMINAL CONTACT WITH PEDESTRIANS LEG.

Occurred on ASHDON ROAD 50 YRDS WEST J/W ELIZABETH WAY, SAFFRON WALDEN

Vehicle Reference 1 Car Starting
 Vehicle movement from W to E No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 55 Female
 Not hit and run Breath test Not requested
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 19 Male Pedestrian Severity: Slight
 Not a pupil Postcode Seatbelt
 In carr elsewhere E bound
 Driver's nearside

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I17430511 18/05/2011 Time 1340 Vehicles 2 Casualties 1 Slight
 E: 554533 N: 237547 First Road: U Road Type Single carriageway
 Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
 Crossing: Control None Facilities: None within 50m Road surface Dry
 Daylight:street lights present Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: Elsewhere DfT Special Projects:

Causation		Participant:	Confidence:
Factor:			
1st:	Poor turn or manoeuvre	Vehicle 1	Very Likely
2nd:	Failed to look properly	Vehicle 1	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEH 2 STATIONARY BEHIND PARKED CARS WAITING FOR BUS TO PASS. VEH 1 HAS COME OTU OF SIDE RD OLD MILL RD AND COLLIDED WITH REAR OF VEH 2. VEH 1 HAS THEN REVERSED AND PULLED OUT AROUND REAR OF VEH 2 AND DRIVEN UP WINSTANLEY RD.

Occurred on WINSTANLEY RD J/W OLD MILL RD

Vehicle Reference 1 Car Turning right
 Vehicle movement from W to S No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Entering main road First impact Front Hit vehicle: 2
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 23 Male
 Hit and run Breath test Driver not contacted
 Driver Postcode: VRM:

Vehicle Reference 2 Car Going ahead but held up
 Vehicle movement from S to N No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Mid Junction - on roundabout or i First impact Back Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 48 Female
 Not hit and run Breath test Driver not contacted
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 2 Age: 48 Female Driver/rider Severity: Slight
 Not a pupil Postcode Seatbelt

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I40781011 21/10/2011 Time 0630 Vehicles 2 Casualties 1 Serious
 E: 554444 N: 238268 First Road: B 184 Road Type Single carriageway
 Speed limit: 30 Junction Detail: Not within 20m of junction Not applicable
 Crossing: Control None Facilities: Pelican, puffin, toucan etc. Road surface Dry
 Darkness: street lighting unknown Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: Elsewhere DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Failed to judge vehicles path or speed	Casualty 1	Very Likely	
2nd: Failed to look properly	Vehicle 2	Possible	
3rd:			
4th:			
5th:			
6th:			

VEH 2 WAS APPROX 30 MTRS FROM J/W HARRIS YARD WHEN PEDAL CYCLE HAS COME OUT OF ADDRESS AND COLLIDED WITH O/S FRONT WING OF VEH 2 AND GONE DOWN O/S OF VEH .

Occurred on THAXTED ROAD APPROX 30 MTRS PRIOR TO J/W HARRIS YARD SAFFRON WALDEN

Vehicle Reference 1 Pedal Cycle Going ahead other
 Vehicle movement from S to N No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Not at, or within 20M of Jct First impact Did not impact Hit vehicle: 2
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 14 Male
 Not hit and run Breath test Not requested
 Driver Postcode: VRM:

Vehicle Reference 2 Car Going ahead other
 Vehicle movement from Park to Parked No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Not at, or within 20M of Jct First impact Nearside Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 25 Male
 Not hit and run Breath test Driver not contacted
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 2 Age: 14 Male Pedestrian Severity: Serious
 Not a pupil Postcode Seatbelt
 Location U/K E bound
 Movement U/K

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I34351011 26/10/2011 Time 1230 Vehicles 2 Casualties 1 Slight
 E: 554004 N: 239031 First Road: B 1052 Road Type Dual carriageway
 Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
 Crossing: Control None Facilities: None within 50m Road surface Dry
 Daylight:street lights present Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Failed to look properly	Vehicle 1	Very Likely	
2nd: Loss of control	Vehicle 1	Possible	
3rd: Uncorrected, defective eyesight	Vehicle 1		
4th:			
5th:			
6th:			

VEH 2 PARKED AND UNATTENDED ON CORRECT SIDE OF ROAD, VEH 1 HAS APPROACHED FROM BEHIND AND FOR AN UNKNOWN REASON HAS COLLIDED INTO REAR OF STATIONARY VEH 2.

Occurred on LITTLE WALDEN ROAD J/W THE GREEN

Vehicle Reference 1 Car Starting
 Vehicle movement from E to W No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Leaving roundabout First impact Did not impact Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 73 Female
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 73 Female Driver/rider Severity: Slight
 Not a pupil Postcode Seatbelt

Vehicle Reference 2 Car Parked
 Vehicle movement from Park to Parked No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Jct Approach First impact Back Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver Not traced
 Not hit and run Breath test Driver not contacted
 Driver Postcode: VRM:

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I39181111 30/11/2011 Time 0935 Vehicles 2 Casualties 1 Serious
 E: 553440 N: 238758 First Road: B 184 Road Type Single carriageway
 Speed limit: 60 Junction Detail: T & Stag Jct Give way or controlled Unclassified
 Crossing: Control None Facilities: None within 50m Road surface Dry
 Daylight:street lights present Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Failed to look properly	Vehicle 1	Very Likely	
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 TURNING INTO NEW POND LANE. FOR REASONS UNKNOWN DRIVER DOES NOT SEE VEH 2 TRAVELLING NORTH BOUND ON B184 IN MOUTH OF NEW POND LANE. RIDER OF VEH 2 COLLIDES WITH BONNET OF VEH 1.

Occurred on WINDMILL HILL B184 J/W NEW POND LANE, SAFFRON WALDEN, ESSEX

Vehicle Reference 1 Car Turning right
 Vehicle movement from Park to Parked No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle: 2
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 41 Female
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 41 Female Driver/rider Severity: Serious
 Not a pupil Postcode Seatbelt

Vehicle Reference 2 Pedal Cycle Going ahead other
 Vehicle movement from Park to Parked No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Cleared junction or waiting/parke First impact Back Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 41 Female
 Not hit and run Breath test Driver not contacted
 Driver Postcode: VRM:

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I40291211 05/12/2011 Time 0820 Vehicles 1 Casualties 1 Slight
 E: 554882 N: 238787 First Road: U Road Type Single carriageway
 Speed limit: 30 Junction Detail: Not within 20m of junction Not applicable
 Crossing: Control None Facilities: None within 50m Road surface Dry
 Daylight:street lights present Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Failed to look properly	Casualty 1	Very Likely	
2nd:			
3rd:			
4th:			
5th:			
6th:			

CAS WAS ON HIS WAY TO SCHOOL. HE HAD STOPPED ON THE GRASS BETWEEN HARVEY WAY AND WHITESHOT WAY. HE LOOKED RIGHT AND LEFT, CARS WERE COMING UP BOTH WAYS. HE LOOKED LEFT AGAIN TOWARDS ASHDEN AND IT WAS CLEAR BUT HE THEN FORGOT TO LOOK RIGHT AND WALKED OUT INTO THE ROAD. VEH 1 CAUGHT THE CAS ON THE RIGHT LEF AND IT FLIPPED HIM OVER. VEH WAS TRAVELLING FROM COMMON HILL & SAFFRON WALDEN, TOWARDS ASHDON.

Occurred on JUST AFTER GRASS VERGE BETWEEN WHITE SHOT WAY AND HARVEY WAY

Vehicle Reference 1 Car Going ahead other
 Vehicle movement from W to E No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Not at, or within 20M of Jct First impact Did not impact Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 32 Female
 Not hit and run Breath test Not requested
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 14 Male Pedestrian Severity: Slight
 School pupil to/from school Postcode Seatbelt
 On footpath / verge Direction Unknown
 Movement U/K

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I40151211 08/12/2011 Time 2040 Vehicles 1 Casualties 1 Slight
 E: 553781 N: 238215 First Road: B 184 Road Type Single carriageway
 Speed limit: 30 Junction Detail: Other Give way or controlled
 Crossing: Control None Facilities: Central reservation Road surface Wet/Damp
 Darkness: street lights present and lit Unknown
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: Elsewhere DfT Special Projects:

Causation		
Factor:	Participant:	Confidence:
1st: Careless/Reckless/In a hurry	Vehicle 1	Very Likely
2nd:		
3rd:		
4th:		
5th:		
6th:		

CAS 1 WAS CROSSING THE ROAD AT THE TOP OF THE HIGH STREET IN SAFFRON WALDEN. CAS 1 HAD JUST LEFT THE FRIENDS MEETING HOUSE. CAS CROSSED THE ROAD AND WAS STANDING WAITING TO CROSS THE REMAINDER OF THE ROAD ON THE TRAFFIC ISLAND OPPOSITE TO GOLD STREET . A VEH COMING DOWN THE STREET TRAVELLING AT SPEED HIT CAS 1'S WALKING STICK WHICH CAUSED CAS TO FALL INTO THE TRAFFIC ISLAND AND CAUSE CAS INJURY.

Occurred on TRAFFIC ISLAND ON THE B184 HIGH STREET, SAFFRON WALDEN, OPPOSITE GOLD STREET

Vehicle Reference 1 Car Going ahead other
 Vehicle movement from N to S No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Jct Approach First impact Did not impact Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver Not traced
 Hit and run Breath test Driver not contacted
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 77 Male Pedestrian Severity: Slight
 Not a pupil Postcode Seatbelt
 On refuge Standing still
 Driver's offside

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I03950112 06/01/2012 Time 0950 Vehicles 1 Casualties 1 Slight
 E: 553706 N: 238452 First Road: B 184 Road Type Single carriageway
 Speed limit: 50 Junction Detail: Not within 20m of junction Not applicable
 Crossing: Control None Facilities: None within 50m Road surface Dry
 Daylight:street lights present Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Careless/Reckless/In a hurry	Casualty 1	Possible	
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 PARKED STATIONARY IN HIGH STREET, SAFFRON WALDEN. CAS 1 APPROACHED DRIVER OF VEH 1 FOLLOWING ROAD RAGE INCIDENT. VEH 1 THEN DROVE OFF AND O/S WING MIRROR STRUCK CAS 1.

Occurred on SAFFRON WALDEN B184 HIGH STREET APPROX 200 YRDS SOUTH J/W CASTLE STREET.

Vehicle Reference 1 Car Going ahead but held up
 Vehicle movement from N to S No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Not at, or within 20M of Jct First impact Did not impact Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 60 Male
 Not hit and run Breath test Driver not contacted
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 67 Male Pedestrian Severity: Slight
 Not a pupil Postcode Seatbelt
 In carr elsewhere E bound
 Driver's offside

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I02420112 28/01/2012 Time 1118 Vehicles 2 Casualties 1 Slight
 E: 553559 N: 237885 First Road: B 1052 Road Type Single carriageway
 Speed limit: 30 Junction Detail: Roundabout Give way or controlled Unclassified
 Crossing: Control None Facilities: None within 50m Road surface Dry
 Daylight:street lights present Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation		Participant:	Confidence:
Factor:			
1st:	Disobeyed Give Way or Stop sign or markings	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH TRAVELLING AUDLEY END ROAD TOWARDS SAFFRON WALDEN TOWN CENTRE FAILS TO GIVE WAY TO PEDAL CYCLE VEH 2 WHICH IS ALREADY ON RAB NO ACTUAL IMPACT HOWEVER VEH 1 ACTIONS CAUSED RIDER OF VEH 2 TO FALL OFF.

Occurred on NEWPORT ROAD J/W AUDLEY END

Vehicle Reference 1 Car Starting
 Vehicle movement from W to NE No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Entering roundabout First impact Did not impact Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 46 Female
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Vehicle Reference 2 Pedal Cycle Starting
 Vehicle movement from S to N No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Entering roundabout First impact Did not impact Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 65 Male
 Not hit and run Breath test Driver not contacted
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 2 Age: 65 Male Driver/rider Severity: Slight
 Not a pupil Postcode Seatbelt

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I19150612 21/06/2012 Time 1800 Vehicles 1 Casualties 1 Slight
 E: 554641 N: 237653 First Road: U Road Type Single carriageway
 Speed limit: 30 Junction Detail: Not within 20m of junction Not applicable
 Crossing: Control None Facilities: Central reservation Road surface Wet/Damp
 Daylight:street lights present Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: Elsewhere DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Passing too close to cyclist, horse rider or pedestrian	Vehicle 1	Possible	
2nd:			
3rd:			
4th:			
5th:			
6th:			

PED WAS WALKING ALONG PEASLAND RD TOWARDS THAXTED RD WHEN PED RIGHT ARM WAS STRUCK BY THE N/S WING MIRROR OF VEH 1 CAUSING INJURY TO PED. VEH 1 STOPPED FURTHER DOWN THE RD JUST BEFORE THE R/A.

Occurred on PEASLAND RD APPROX 58M FROM J/E THAXTED RD

Vehicle Reference 1 Car Going ahead other
 Vehicle movement from W to E No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Not at, or within 20M of Jct First impact Nearside Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 76 Female
 Not hit and run Breath test Driver not contacted
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 22 Female Pedestrian Severity: Slight
 Not a pupil Postcode Seatbelt
 On footpath / verge E bound
 Movement U/K

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I23530712 31/07/2012 Time 0024 Vehicles 2 Casualties 1 Slight
 E: 553736 N: 238349 First Road: B 184 Road Type 2
 Speed limit: 30 Junction Detail: Not within 20m of junction Not applicable
 Crossing: Control None Facilities: None within 50m Road surface Dry
 Darkness: street lighting unknown Unknown
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: Elsewhere DfT Special Projects:

	Factor:	Causation	Participant:	Confidence:
1st:				
2nd:				
3rd:				
4th:				
5th:				
6th:				

VEH 2 WAS PARKED STATIONARY AT ABOVE LOCATION. VEH 1 COLLIDED WITH REAR OF VEH 2 THEN MADE OFF FAILING TO STOP.

Occurred on HIGH ST, SAFFRON WALDEN 400 YRDS FROM J/W GEORGE ST

Vehicle Reference 1 Car Going ahead other
 Vehicle movement from Park to Parked No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Not at, or within 20M of Jct First impact Back Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver Male
 Hit and run Breath test Driver not contacted
 Driver Postcode: VRM:

Vehicle Reference 2 Car Parked
 Vehicle movement from Park to Parked No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Not at, or within 20M of Jct First impact Did not impact Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 44 Male
 Not hit and run Breath test Driver not contacted
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 2 Age: 44 Male Driver/rider Severity: Slight
 Not a pupil Postcode Seatbelt

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I25050812 14/08/2012 Time 1218 Vehicles 1 Casualties 1 Serious
 E: 553727 N: 238387 First Road: B 184 Road Type Single carriageway
 Speed limit: 30 Junction Detail: Crossroads Automatic traffic signal Unclassified
 Crossing: Control None Facilities: None within 50m Road surface Dry
 Daylight:street lights present Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Casualty 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 WAS TRAVELLING DWN HIGH ST APPROACHING ITS J/W GEORGE ST PED HAS STEPPED OUT IN FRONT OF VEH 1.

Occurred on HIGH ST J/W GEORGE ST

Vehicle Reference 1 Car Starting
 Vehicle movement from N to S No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Jct Approach First impact Front Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 35 Female
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 73 Male Pedestrian Severity: Serious
 Not a pupil Postcode Seatbelt
 In carr elsewhere Direction Unknown
 Driver's nearside

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I31261012 04/10/2012 Time 0830 Vehicles 2 Casualties 1 Slight
 E: 553558 N: 237887 First Road: B 1052 Road Type 1
 Speed limit: 30 Junction Detail: Roundabout Give way or controlled Unclassified
 Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
 Daylight:street lights present Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Slippery road (due to weather)	Vehicle 002	Very Likely	
2nd: Dazzling sun	Vehicle 001	Possible	
3rd: Dazzling sun	Vehicle 002	Possible	
4th: Inexperienced or learner driver/rider	Vehicle 002	Possible	
5th: Failed to judge other persons path or speed	Vehicle 001	Possible	
6th:			

DRIVER OF V1 WAS TRAVELLING FROM NEWPORT ROAD WAS TURNING RIGHT AT ROUNDABOUT ONTO LONDON ROAD. V2 CROSSED MINI ROUNDABOUT AT SAME TIME SCRAPPING THE SIDE OF V1. RIDER OF V2 HAS THEN LOST CONTROL AND COME OFF HIS MOTORCYCLE, SLIGHT INJURIES TO RIDER FROM GRAZING THE ROAD, NO INJURIES TO V1 DRIVER.

Occurred on NEWPORT ROAD 10 METRES FROM AUDLEY END ROAD.

Vehicle Reference 1 Car Going ahead other
 Vehicle movement from N to SW No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Entering roundabout First impact Did not impact Hit vehicle: 002
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 51 Female
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Vehicle Reference 2 Motorcycle 50cc and under Going ahead other
 Vehicle movement from W to E No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Entering roundabout First impact Offside Hit vehicle: 001
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 18 Male
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 2 Age: 18 Male Driver/rider Severity: Slight
 Not a pupil Postcode Seatbelt

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I33821012 13/10/2012 Time 1500 Vehicles 1 Casualties 1 Slight
 E: 553780 N: 238187 First Road: B 184 Road Type Single carriageway
 Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
 Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
 Daylight: street lighting unknown Raining without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: Elsewhere DfT Special Projects:

	Factor:	Causation	Participant:	Confidence:
1st:				
2nd:				
3rd:				
4th:				
5th:				
6th:				

V1 WAS LOOKING TO TURN RIGHT OUT OF MARGARET WAY ON TO SAFFRON WALDEN, HIGH STREET. AS V1 HAS BEGUN TO MOVE FORWARD TO TURN RIGHT, THE DRIVER HAS NOT LOOKED LEFT BEFORE MOVING AND HE HAS STRUCK C1 AT A VERY LOW SPEED CAUSING HER TO LOOSE HER BALANCE AND FALL OVER.

Occurred on MARGARET WAY J/W HIGH STREET.

Vehicle Reference 1 Car Waiting to turn right
 Vehicle movement from Park to Parked No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Jct Approach First impact Did not impact Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 66 Female
 Not hit and run Breath test Driver not contacted
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 89 Female Pedestrian Severity: Slight
 Not a pupil Postcode Seatbelt
 Location U/K Direction Unknown
 Movement U/K

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I00060113 02/01/2013 Time 1305 Vehicles 1 Casualties 1 Slight
 E: 554513 N: 238175 First Road: B 184 Road Type Single carriageway
 Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
 Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
 Daylight:street lights present Raining without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Failed to look properly	Casualty 1	Very Likely	
2nd: Careless/Reckless/In a hurry	Casualty 1	Possible	
3rd:			
4th:			
5th:			
6th:			

VEH 1 WAS TRAVELLING DOWN THAXTED ROAD IN GENERAL DIRECTION OF TOWN CENTRE AS VEH APPROACHED J/W VICTORIA AVENUE TRAVELLING AT APPROX 20-25MPH, PEDESTRIAN RAN ACROSS ROAD FROM VEHS NEARSIDE WITHOUT LOOKING, HITTING VEH 1 ON FRONT NEARSIDE.

Occurred on B184 THAXTED ROAD, SAFFRON WALDEN AT J/W VICTORIA AVENUE AND APPROX 100 YRDS :

Vehicle Reference 1 Car Going ahead other
 Vehicle movement from S to N No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Jct Approach First impact Nearside Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 75 Male
 Not hit and run Breath test Not requested
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 12 Male Pedestrian Severity: Slight
 Not a pupil Postcode Seatbelt
 In carr elsewhere E bound
 Driver's nearside

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I02820213 05/02/2013 Time 1900 Vehicles 1 Casualties 1 Slight
 E: 554565 N: 238076 First Road: B 184 Road Type Single carriageway
 Speed limit: 30 Junction Detail: Not within 20m of junction
 Crossing: Control None Facilities: Zebra crossing Road surface Wet/Damp
 Darkness: street lights present and lit Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation		Participant:	Confidence:
Factor:			
1st:	Failed to look properly	Vehicle 001	Possible
2nd:			
3rd:			
4th:			
5th:			
6th:			

V1 TRAVELLING TOWARDS SAFFRON WALDEN ALONG THE B184. AS IT TRAVELLED OVER A ZEBRA CROSSING IT STRUCK A GLANCING BLOW TO A PEDESTRIAN.

Occurred on B184 THAXTED ROAD 100 YARDS SOUTH J/W PROSPECT PLACE.

Vehicle Reference 1 Car Going ahead other
 Vehicle movement from Park to Parked No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 28 Female
 Not hit and run Breath test Not requested
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 38 Male Pedestrian Severity: Slight
 Not a pupil Postcode Seatbelt
 On Ped Crossing W bound
 Driver's offside

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I07730213 20/02/2013 Time 1420 Vehicles 1 Casualties 1 Slight
 E: 554911 N: 238806 First Road: U Road Type Single carriageway
 Speed limit: 30 Junction Detail: Other Give way or controlled Unclassified
 Crossing: Control None Facilities: None within 50m Road surface Dry
 Daylight:street lights present Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Failed to look properly	Casualty 001	Very Likely	
2nd: Careless/Reckless/In a hurry	Casualty 001	Very Likely	
3rd:			
4th:			
5th:			
6th:			

V1 TRAVELLING IN EASTERLY DIRECTION, PEDESTRIAN (C1) RUNS IN FRONT OF V1 CAUSING A COLLISION. DRIVER OF V1 TRIED TO AVOID BY SWERVING BUT CAUGHT C1 ON THE OFF SIDE WING OF V1.

Occurred on ASHDON ROAD J/W WHITESHOT WAY.

Vehicle Reference 1 Car Going ahead other
 Vehicle movement from SW to NE No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Mid Junction - on roundabout or T First impact Front Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 61 Male
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 12 Male Pedestrian Severity: Slight
 Not a pupil Postcode Seatbelt
 In carr elsewhere NW bound
 Driver's offside

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I04620213 20/02/2013 Time 0630 Vehicles 2 Casualties 1 Slight
 E: 554002 N: 238978 First Road: B 1052 Road Type Single carriageway
 Speed limit: 60 Junction Detail: Not within 20m of junction
 Crossing: Control None Facilities: None within 50m Road surface Dry
 Darkness: no street lighting Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: Elsewhere DfT Special Projects:

Causation			
Factor:		Participant:	Confidence:
1st:	Failed to judge other persons path or speed	Vehicle 001	Possible
2nd:	Failed to judge other persons path or speed	Vehicle 002	Possible
3rd:			
4th:			
5th:			
6th:			

V1 WAS TRAVELLING TOWARDS SAFFRON WALDEN, V2 HAS SUDDENLY APPROACHED AND HAS DRIFTED ONTO V1'S SIDE OF THE ROAD, AS HE WAS GOING ROUND A RIGHT HAND BEND. WING MIRRORS HAVE COLLIDED.V2 HAS FAILED TO STOP. V1'S WING MIRROR AND SMALL DRIVERS DOOR WINDOW HAS SHATTERED.

Occurred on JUST BEFORE SAFFRON WALDEN ON B1052 AFTER BIRD BROOKE FARM TURNING.

Vehicle Reference 1 Van or Goods 3.5 tonnes mgw and under Going ahead left bend
 Vehicle movement from N to S No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Not at, or within 20M of Jct First impact Offside Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 32 Male
 Not hit and run Breath test Driver not contacted
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 32 Male Driver/rider Severity: Slight
 Not a pupil Postcode Seatbelt

Vehicle Reference 2 Van or Goods 3.5 tonnes mgw and under Going ahead right bend
 Vehicle movement from S to N No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Not at, or within 20M of Jct First impact Offside Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver Male
 Not hit and run Breath test Driver not contacted
 Driver Postcode: VRM:

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I08160313 27/03/2013 Time 1635 Vehicles 1 Casualties 1 Slight
 E: 555083 N: 238458 First Road: B 1053 Road Type Single carriageway
 Speed limit: 30 Junction Detail: Not within 20m of junction
 Crossing: Control None Facilities: Central reservation Road surface Dry
 Daylight:street lights present Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Failed to look properly	Casualty 001	Very Likely	
2nd:			
3rd:			
4th:			
5th:			
6th:			

V1 TRAVELLING WEST ALONG RADWINTER ROAD WHEN C1 WALKS OUT INTO THE ROAD FROM THE NEARSIDE INTO THE PATH OF V1. V1 ATTEMPTED TO AVOID C1 BY STEERING TO THE RIGHT BUT FAILED TO AVOID C1.

Occurred on RADWINTER ROAD 50 METRES EAST OF FERGUSON CLOSE.

Vehicle Reference 1 Car Going ahead other
 Vehicle movement from W to E No tow / articulation
 On main carriageway Skidded
 Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 37 Male
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 10 Female Pedestrian Severity: Slight
 School pupil to/from school Postcode Seatbelt
 In carr elsewhere E bound
 Driver's nearside

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I09740413 10/04/2013 Time 1345 Vehicles 2 Casualties 1 Slight
 E: 554004 N: 239028 First Road: B 1052 Road Type 1
 Speed limit: 30 Junction Detail: Roundabout Give way or controlled Unclassified
 Crossing: Control None Facilities: None within 50m Road surface Dry
 Daylight:street lights present Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation		Participant:	Confidence:
Factor:			
1st:	Failed to look properly	Vehicle 002	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

V1 IS APPROACHING A MINI ROUNDABOUT HAVING JUST PASSED THE CYCLIST. THE VEHICLE HAS TO SLOW DUE TO OTHER TRAFFIC. THE PEDAL CYCLIST FAILS TO SEE THIS VEHICLE SLOWING IN TIME AND HAS TO EMERGENCY BRAKE, THIS HAS CAUSED HIM TO GO OVER THE HANDLEBARS AND LAND ON THE ROAD ON HIS FACE.

Occurred on LITTLE WALDEN ROAD J/W GODDARD ROAD

Vehicle Reference 1 Car Stopping
 Vehicle movement from Park to Parked No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Jct Approach First impact Did not impact Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 43 Male
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Vehicle Reference 2 Pedal Cycle Stopping
 Vehicle movement from Park to Parked No tow / articulation
 On main carriageway Skidded
 Location at impact Jct Approach First impact Did not impact Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 17 Male
 Not hit and run Breath test Not applicable
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 2 Age: 17 Male Driver/rider Severity: Slight
 Not a pupil Postcode Seatbelt

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I20410713 19/07/2013 Time 1345 Vehicles 1 Casualties 1 Slight
 E: 554773 N: 238759 First Road: U Road Type Single carriageway
 Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
 Crossing: Control None Facilities: None within 50m Road surface Dry
 Daylight Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Failed to look properly	Casualty 001	Very Likely	
2nd: Careless/Reckless/In a hurry	Casualty 001	Possible	
3rd:			
4th:			
5th:			
6th:			

THE VEHICLE WAS TRAVELLING AWAY FROM SAFFRON WALDEN AND AS THE VEHICLE DROVE PAST 2 PARKED VEHICLES THE SCHOOL GIRL HAS STEPPED OUT FROM BEHIND THE PARKED VEHICLES AND THE DRIVER COLLIDED WITH HER.

Occurred on ASHDON ROAD, NEAR TO JUNCTION OF HARVEY WAY.

Vehicle Reference 1 Car Going ahead other
 Vehicle movement from W to E No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Jct Approach First impact Front Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 21 Female
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 12 Female Pedestrian Severity: Slight
 Not a pupil Postcode Seatbelt
 In carr elsewhere N bound
 Driver's offside masked

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I21300713 24/07/2013 Time 1721 Vehicles 2 Casualties 1 Slight
 E: 554177 N: 239094 First Road: U Road Type Single carriageway
 Speed limit: 30 Junction Detail: Not within 20m of junction
 Crossing: Control None Facilities: None within 50m Road surface Dry
 Daylight Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Failed to look properly	Casualty 1	Very Likely	
2nd: Stationary or parked vehicle	Casualty 1	Very Likely	
3rd: Stationary or parked vehicle	Vehicle 2	Very Likely	
4th: Failed to look properly	Vehicle 2	Very Likely	
5th:			
6th:			

VEH 1 STOPPED ALONG GODDARD WAY AND TWO PASSENGERS ALIGHTED FROM THE VEH TO THE PATH, CAS 1 WALKED AROUND THE FRONT OF VEH 1 AND BEGAN TO CROSS THE ROAD WHERE SHE COLLIDED WITH VEH 2 THAT WAS OVERTAKING VEH 1.

Occurred on GODDARD WAY, 40 METRES FROM J/W SHRUBLANDS

Vehicle Reference 1 Car Parked
 Vehicle movement from Park to Parked No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Not at, or within 20M of Jct First impact Did not impact Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 47 Male
 Not hit and run Breath test Driver not contacted
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 13 Female Pedestrian Severity: Slight
 Not a pupil Postcode Seatbelt
 In carr elsewhere Direction Unknown

Driver's nearside

Vehicle Reference 2 Car Overtaking stat vehicle O/S
 Vehicle movement from Park to Parked No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Not at, or within 20M of Jct First impact Nearside Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 25 Male
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection: Notes:

Selected using Build Query :

I24950813 24/08/2013 Time 1715 Vehicles 2 Casualties 1 Slight
 E: 554155 N: 237964 First Road: U Road Type Single carriageway
 Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
 Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
 Daylight Fine without high winds
 Special Conditions at Site None Carriageway Hazards: None
 Place accident reported: At scene DfT Special Projects:

Causation			
Factor:	Participant:	Confidence:	
1st: Stationary or parked vehicle	Vehicle 001	Very Likely	
2nd: Careless/Reckless/In a hurry	Vehicle 002	Possible	
3rd: Failed to look properly	Vehicle 001	Very Likely	
4th: Failed to look properly	Vehicle 002	Very Likely	
5th:			
6th:			

V1 TURNING RIGHT FROM WEST ROAD INTO SOUTH ROAD. V2 TRAVELLING ALONG SOUTH ROAD TOWARDS THE TOWN. V1 HAS HAD HIS VIEW OBSCURED BY PARKED VEHICLES. THE F/O/S OF V1 HAS COLLIDED WITH THE F/O/S OF V2.

Occurred on SOUTH ROAD SAFFRON WALDEN J/W WEST ROAD.

Vehicle Reference 1 Car Turning right
 Vehicle movement from W to S No tow / articulation
 On main carriageway No skidding, jack-knifing or overturning
 Location at impact Mid Junction - on roundabout or T First impact Offside Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 55 Male
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Casualty Reference: 1 Vehicle: 1 Age: 55 Male Driver/rider Severity: Slight
 Not a pupil Postcode Seatbelt

Vehicle Reference 2 Car Going ahead other
 Vehicle movement from S to N No tow / articulation
 On main carriageway Skidded
 Location at impact Jct Approach First impact Front Hit vehicle:
 Hit object in road None Off road: None
 Did not leave carr Age of Driver 19 Male
 Not hit and run Breath test Negative
 Driver Postcode: VRM:

Accidents between dates 30/08/2008 and 31/08/2013 (60) months

Selection:

Notes:

Selected using Build Query :

Accidents involving:

	Fatal	Serious	Slight	Total
Motor vehicles only (excluding 2-wheels)	0	5	31	36
2-wheeled motor vehicles	0	0	2	2
Pedal cycles	0	3	3	6
Horses & other	1	0	0	1
Total	1	8	36	45

Casualties:

	Fatal	Serious	Slight	Total
Vehicle driver	1	5	16	22
Passenger	0	0	4	4
Motorcycle rider	0	0	2	2
Cyclist	0	1	3	4
Pedestrian	0	2	15	17
Other	0	0	0	0
Total	1	8	40	49

Appendix I


Census Distribution Data and Distribution Diagram

Radwinter Distributions




area of worT203:27 (Car - driver : Not full-time student: in employment full-time)


Area of workplace : 2003 CAS ward	Local Authority	Route General	1058	RTL Traffic Signal Controlled Junction Mini Roundabout																																			
				Access				Site Access / Radwinter Road				Radwinter Rd / Elizabeth Way				Elizabeth Way / Ashdon Road				Ashdon Road / B1052 Common Hill / Castle Hill				Shire Hill / Thaxted Road				Radwinter / Thaxted Road				Thaxted Road / Peaslands Road							
				Thax	Rad	53.0%	47.0%	W	E	45.9%	1.1%	W	N	W	N	N	W	37.4%	0.4%	W	N	W	N	31.3%	6.1%	N	S	0.0%	51.3%	S	W	N	0.0%	6.2%	0.0%	W	S	42.7%	8.6%
				560.8	497.2	485.2	12	65.5	400	396	4	331	65	0	543.07	0	65.5	0	452.07	91																			
00BKQG	St James's	London	Radwinter Rd, B184 North, M11South	5	0.5%	1	0	5	1	5	0	1	0	5	1	5	0	1	0	5	1	5	0	1	0	5	1	5	0	1	0	5	1	5	0	1	0	5	1
12UBFQ	Abbey	Cambridge	Radwinter Rd, B184 North, A11 North	4	0.4%	1	0	4	1	4	0	1	0	4	1	4	0	1	0	4	1	4	0	1	0	4	1	4	0	1	0	4	1	4	0	1	0	4	1
12UBFS	Castle	Cambridge	Radwinter Rd, B184 North, A11 North	7	0.7%	1	0	7	1	7	0	1	0	7	1	7	0	1	0	7	1	7	0	1	0	7	1	7	0	1	0	7	1	7	0	1	0	7	1
12UBFT	Cherry Hinton	Cambridge	Radwinter Rd, B184 North, A11 North	4	0.4%	1	0	4	1	4	0	1	0	4	1	4	0	1	0	4	1	4	0	1	0	4	1	4	0	1	0	4	1	4	0	1	0	4	1
12UBFW	East Chesterton	Cambridge	Radwinter Rd, B184 North, A11 North	8	0.8%	1	0	8	1	8	0	1	0	8	1	8	0	1	0	8	1	8	0	1	0	8	1	8	0	1	0	8	1	8	0	1	0	8	1
12UBFX	King's Hedges	Cambridge	Radwinter Rd, B184 North, A11 North	5	0.5%	1	0	5	1	5	0	1	0	5	1	5	0	1	0	5	1	5	0	1	0	5	1	5	0	1	0	5	1	5	0	1	0	5	1
12UBFY	Market	Cambridge	Radwinter Rd, B184 North, A11 North	24	2.3%	1	0	24	1	24	0	1	0	24	1	24	0	1	0	24	1	24	0	1	0	24	1	24	0	1	0	24	1	24	0	1	0	24	1
12UBGA	Petersfield	Cambridge	Radwinter Rd, B184 North, A11 North	6	0.6%	1	0	6	1	6	0	1	0	6	1	6	0	1	0	6	1	6	0	1	0	6	1	6	0	1	0	6	1	6	0	1	0	6	1
12UBGB	Queen Edith's	Cambridge	Radwinter Rd, B184 North, A11 North	18	1.7%	1	0	18	1	18	0	1	0	18	1	18	0	1	0	18	1	18	0	1	0	18	1	18	0	1	0	18	1	18	0	1	0	18	1
12UBGC	Romsey	Cambridge	Radwinter Rd, B184 North, A11 North	4	0.4%	1	0	4	1	4	0	1	0	4	1	4	0	1	0	4	1	4	0	1	0	4	1	4	0	1	0	4	1	4	0	1	0	4	1
12UBGD	Trumpington	Cambridge	Radwinter Rd, B184 North, A11 North	18	1.7%	1	0	18	1	18	0	1	0	18	1	18	0	1	0	18	1	18	0	1	0	18	1	18	0	1	0	18	1	18	0	1	0	18	1
12UBGE	West Chesterton	Cambridge	Radwinter Rd, B184 North, A11 North	4	0.4%	1	0	4	1	4	0	1	0	4	1	4	0	1	0	4	1	4	0	1	0	4	1	4	0	1	0	4	1	4	0	1	0	4	1
12UGGW	Balsham	South Cambrdge	Radwinter Road, B1052 North	4	0.4%	1	0	4	1	4	0	1	0	4	1	4	0	1	0	4	1	4	0	1	0	4	1	4	0	1	0	4	1	4	0	1	0	4	1
12UGHE	Duxford	South Cambrdge	Radwinter Road, B184 North	18	1.7%	1	0	18	1	18	0	1	0	18	1	18	0	1	0	18	1	18	0	1	0	18	1	18	0	1	0	18	1	18	0	1	0	18	1
12UGHG	Fulbourn	South Cambrdge	Radwinter Rd, B184 North, A11 North	5	0.5%	1	0	5	1	5	0	1	0	5	1	5	0	1	0	5	1	5	0	1	0	5	1	5	0	1	0	5	1	5	0	1	0	5	1
12UGHL	Harston and Hauxton	South Cambrdge	Radwinter Rd, B184 North, A1301 North	4	0.4%	1	0	4	1	4	0	1	0	4	1	4	0	1	0	4	1	4	0	1	0	4	1	4	0	1	0	4	1	4	0	1	0	4	1
12UGHN	Histon and Impington	South Cambrdge	Radwinter Rd, B184 North, A1301 North	5	0.5%	1	0	5	1	5	0	1	0	5	1	5	0	1	0	5	1	5	0	1	0	5	1	5	0	1	0	5	1	5	0	1	0	5	1
12UGHP	Linton	South Cambrdge	Radwinter Road, B1052 North	6	0.6%	1	0	6	1	6	0	1	0	6	1	6	0	1	0	6	1	6	0	1	0	6	1	6	0	1	0	6	1	6	0	1	0	6	1
12UGHR	Melbourn	South Cambrdge	Radwinter Rd, B184 North, A1301 North	8	0.8%	1	0	8	1	8	0	1	0	8	1	8	0	1	0	8	1	8	0	1	0	8	1	8	0	1	0	8	1	8	0	1	0	8	1
12UGHT	Milton	South Cambrdge	Radwinter Rd, B184 North, A1301 North	5	0.5%	1	0	5	1	5	0	1	0	5	1	5	0	1	0	5	1	5	0	1	0	5	1	5	0	1	0	5	1	5	0	1	0	5	1
12UGHX	Sawton	South Cambrdge	Radwinter Rd, B184 North, A1301 North	36	3.4%	1	0	36	1	36	0	1	0	36	1	36	0	1	0	36	1	36	0	1	0	36	1	36	0	1	0	36	1	36	0	1	0	36	1
12UGIA	The Abingtons	South Cambrdge	Radwinter Road, B1052 North	55	5.2%	1	0	55	1	55	0	1	0	55	1	55	0	1	0	55	1	55	0	1	0	55	1	55	0	1	0	55	1	55	0	1	0	55	1
12UGIC	The Shelfords and Stapleford	South Cambrdge	Radwinter Rd, B184 North, A1301 North	8	0.8%	1	0	8	1	8	0	1	0	8	1	8	0	1	0	8	1	8	0	1	0	8	1	8	0	1	0	8	1	8	0	1	0	8	1
12UGID	The Wilbrahams	South Cambrdge	Radwinter Rd, B184 North, A11 North	5	0.5%	1	0	5	1	5	0	1	0	5	1	5	0	1	0	5	1	5	0	1	0	5	1	5	0	1	0	5	1	5	0	1	0	5	1
12UGJF	Whittlesford	South Cambrdge	Radwinter Rd, B184 North, A1301 North	10	0.9%	1	0	10	1	10	0	1	0	10	1	10	0	1	0	10	1	10	0	1	0	10	1	10	0	1	0	10	1	10	0	1	0	10	1
22UGGJ	Ashdon	Uttlesford	Ashdon Rd East, Walden Rd East	4	0.4%	1	0	4	1	4	0	1	0	4	1	4	0	1	0	4	1	4	0	1	0	4	1	4	0	1	0	4	1	4	0	1	0	4	1
22UGGU	Littlebury	Uttlesford	Radwinter Rd, Ashdon Rd, B184 North	20	1.9%	1	0	20	1	20	0	1	0	20	1	20	0	1	0	20	1	20	0	1	0	20	1	20	0	1	0	20	1	20	0	1	0	20	1
22UGGY	Saffron Walden Castle	Uttlesford	Radwinter Road, B1052 North	69	6.5%	1	0	69	1	69	0	1	0	69	1	69	0	1	0	69	1	69	0	1	0	69	1	69	0	1	0	69	1	69	0	1	0	69	1
22UQHG	The Chesterfords	Uttlesford	Radwinter Rd, Ashdon Rd, B184 North	17	1.6%	1	0	17	1	17	0	1	0	17	1	17	0	1	0	17	1	17	0	1	0	17	1	17	0	1	0	17	1	17	0	1	0	17	1
22UQHK	The Sampfords	Uttlesford	Radwinter Rd East	5	0.5%	1	0	5	1	5	0	1	0	5	1	5	0	1	0	5	1	5	0	1	0	5	1	5	0	1	0	5	1	5	0	1	0	5	1
26UFHB	Royston Heath	North Hertfordshire	Radwinter Rd, B184, A1301, A505	14	1.3%	1	0	14	1	14	0	1	0	14	1	14	0	1	0	14	1	14	0	1	0	14	1	14	0	1	0	14	1	14	0	1	0	14	1
42UFGZ	Haverhill South	St Edmundsbury	Radwinter Rd east, B1054, B1057	7	0.7%	1	0	7	1	7	0	1	0	7	1	7	0	1	0	7	1	7	0	1	0	7	1	7	0	1	0	7	1	7	0	1	0	7	1
22UGGX	Saffron Walden Audley	Uttlesford	Radwinter Rd, Ashdon Rd, B1052 South	131	12.4%	0.5	0.5	65.5	1	65.5	0	1	0	65.5	0	65.5	0	1	0	65.5	0	65.5	0	1	0	65.5	0	65.5	0	1	0	65.5	0	65.5	0	1	0	65.5	0
22UGGZ	Saffron Walden Shire	Uttlesford	Radwinter Rd, B184 South	197	18.6%	0.9	0.1	177.3	1	197	0	1	0	197	0	197	0	1	0	197	0	197	0	1	0	197	0	197	0	1	0	197	0	197	0	1	0	197	0
22UHGG	Epping Lindsey and Thornwood Common	Epping Forest	Thaxted Road	4	0.4%	1	0	4	0	4	0	1	0	4	0	4	0	1	0	4	0	4	0	1	0	4	0	4	0	1	0	4	0	4	0	1	0	4	0
22UJFX	Little Parndon and Hare Street	Harlow	Thaxted Rd, B1052, B1383, M11 South	20	1.9%	1	0	20	0	20	0	1	0	20	0	20	0	1	0	20	0	20	0	1	0	20	0	20	0	1	0	20	0	20	0	1	0	20	0
22UJFY	Mark Hall	Harlow	Thaxted Rd, B1052, B1383, M11 South	11	1.0%	1	0	11	0	11																													


Appendix J
Vehicle Trip Diagrams
JPP drawings R6694PP-TA20-29




KEY




-  All arrows indicate a one way system
-  Dead End
-  Site Layout





 <p>Civil & Structural Engineers</p> <p>Cedar Barn, White Lodge, Walgrave, Northampton NN6 9PY</p> <p>T: (01604) 781811 E: mail@jppuk.net F: (01604) 781999 W: www.jppuk.net</p>	Client	Manor Oak Homes
	Project	Radwinter Road Saffron Walden
	Title	Vehicle Trips AM Background 2018
Scale at A3	NTS	Drawn by DL
	Checked by MJA	Date December 2013
Status	Project ref	Drawing no. Revision
For Information	R6694/PP	TA20




KEY




-  All arrows indicate a one way system
-  Dead End
-  Site Layout





 <p>Civil & Structural Engineers</p> <p>Cedar Barn, White Lodge, Walgrave, Northampton NN6 9PY</p> <p>T: (01604) 781811 E: mail@jppuk.net F: (01604) 781999 W: www.jppuk.net</p>	Client	Manor Oak Homes
	Project	Radwinter Road Saffron Walden
	Title	Vehicle Trips AM Committed Development
Scale at A3	NTS	Drawn by DL
	Checked by MJA	Date December 2013
Status	Project ref	Drawing no. Revision
For Information	R6694/PP	TA21




KEY




-  All arrows indicate a one way system
-  Dead End
-  Site Layout





 <p>jpp consulting Civil & Structural Engineers</p> <p>Cedar Barn, White Lodge, Walgrave, Northampton NN6 9PY</p> <p>T: (01604) 781811 E: mail@jppuk.net F: (01604) 781999 W: www.jppuk.net</p>	Client Manor Oak Homes		
	Project Radwinter Road Saffron Walden		
	Title Vehicle Trips AM 2018 + Background + Committed		
Scale at A3 NTS	Drawn by DL	Checked by MJA	Date December 2013
Status For Information	Project ref R6694/PP	Drawing no. TA22	Revision




KEY

-  All arrows indicate a one way system
-  Dead End
-  Site Layout




 <p>jpp consulting Civil & Structural Engineers</p> <p>Cedar Barn, White Lodge, Walgrave, Northampton NN6 9PY</p> <p>T: (01604) 781811 E: mail@jppuk.net F: (01604) 781999 W: www.jppuk.net</p>	Client	Manor Oak Homes
	Project	Radwinter Road Saffron Walden
	Title	Vehicle Trips AM Development Traffic
Scale at A3	NTS	Drawn by DL
	Checked by MJA	Date December 2013
Status	Project ref	Drawing no. Revision
For Information	R6694/PP	TA23




KEY




- All arrows indicate a one way system
- Dead End
- Site Layout





<p style="font-size: small; margin-top: 5px;">Civil & Structural Engineers</p> <p style="font-size: x-small; margin-top: 5px;">Cedar Barn, White Lodge, Walgrave, Northampton NN6 9PY</p> <p style="font-size: x-small; margin-top: 5px;">T: (01604) 781811 E: mail@jppuk.net F: (01604) 781999 W: www.jppuk.net</p>	Client Manor Oak Homes		
	Project Radwinter Road Saffron Walden		
	Title Vehicle Trips AM Background 2018 + Committed + Development		
Scale at A3 NTS	Drawn by DL	Checked by MJA	Date December 2013
Status For Information	Project ref R6694/PP	Drawing no. TA24	Revision




KEY




-  All arrows indicate a one way system
-  Dead End
-  Site Layout





 <p>jpp consulting Civil & Structural Engineers</p> <p>Cedar Barn, White Lodge, Walgrave, Northampton NN6 9PY</p> <p>T: (01604) 781811 E: mail@jppuk.net F: (01604) 781899 W: www.jppuk.net</p>	Client Manor Oak Homes		
	Project Radwinter Road Saffron Walden		
	Title Vehicle Trips PM Background 2018		
Scale at A3 NTS	Drawn by DL	Checked by MJA	Date December 2013
Status For Information	Project ref R6694/PP	Drawing no. TA25	Revision




KEY




-  All arrows indicate a one way system
-  Dead End
-  Site Layout





 <p>jpp consulting Civil & Structural Engineers</p> <p>Cedar Barn, White Lodge, Walgrave, Northampton NN6 9PY</p> <p>T: (01604) 781811 E: mail@jppuk.net F: (01604) 781999 W: www.jppuk.net</p>	Client Manor Oak Homes		
	Project Radwinter Road Saffron Walden		
	Title Vehicle Trips PM Committed Development		
Scale at A3 NTS	Drawn by DL	Checked by MJA	Date December 2013
Status For Information	Project ref R6694/PP	Drawing no. TA26	Revision



KEY

-  All arrows indicate a one way system
-  Dead End
-  Site Layout



 <p>Cedar Barn, White Lodge, Walgrave, Northampton NN6 9PY T: (01604) 781811 E: mail@jppuk.net F: (01604) 781999 W: www.jppuk.net</p>	Client Manor Oak Homes		
	Project Radwinter Road Saffron Walden		
	Title Vehicle Trips PM 2018 + Background + Committed		
Scale at A3 NTS	Drawn by DL	Checked by MJA	Date December 2013
Status For Information	Project ref R6694/PP	Drawing no. TA27	Revision

